

Spring 2020

控制系統
Control Systems

Unit 45


Feedforward Control by Plant Model Inversion

Feng-Li Lian & Ming-Li Chiang

NTU-EE

Mar 2020 – Jul 2020


Feedforward Control by Plant Model Inversion





$$D = G^{-1}$$

$$Y = G U = G (G^{-1} R) = R$$

$$G(s) = \frac{b_1 s + b_2}{s^2 + a_1 s + a_2} \quad G^{-1}(s) = \frac{s^2 + a_1 s + a_2}{b_1 s + b_2}$$



- P Controller yields a steady-state error
- I Controller reduces errors,
but decreases damping/stability
- Use some Feedforward Control



- Feedforward control structure for: (a) tracking; (b) disturbance rejection

- Example 4.10: Feedforward Control for DC motor

$$G(s) = \frac{A}{s^2 + a_1 s + a_2} = \frac{1}{s^2 + 1.4s + 1}$$

$$1 + k_P G(s) = 0$$

$$k_P = 1.5 \text{ or } 6$$

$$\Rightarrow G(0)^{-1} = 1$$

$$Y(s) = G(s) U(s)$$



$$Y(s) = G(s) [k_P E(s) + R(s)]$$

$$E(s) = R(s) - Y(s)$$

$$\mathcal{T}(s) = \frac{Y(s)}{R(s)} = \frac{(1 + k_P) G(s)}{1 + k_P G(s)}$$

$$D_c(s) = k_P$$

- For Tracking



- Example 4.10: Feedforward Control for DC motor
- For Disturbance Rejection

$$G(s) = \frac{A}{s^2 + a_1 s + a_2} = \frac{1}{s^2 + 1.4s + 1}$$

$$1 + k_P G(s) = 0$$

$$k_P = 1.5 \text{ or } 6$$

$$\Rightarrow G(0)^{-1} = 1$$

$$Y(s) = W(s) + G(s) U(s)$$

$$Y(s) = W(s)$$

$$+ G(s) [k_P E(s) - W(s)]$$

$$E(s) = R(s) - Y(s)$$

$$\mathcal{T}_w(s) = \frac{Y(s)}{W(s)} = \frac{1 - G(s)}{1 + k_P G(s)}$$

